SM2258XT B17 NAND Flash F/W & ISP Release Information – Q1115A0

Introduction
This purpose of this document is to provide release information on the SM22X family F/W and ISP release information

Fix Coverage
■ stands for the **"new fix"** or **"new support"** in the category
☐ stands for the **"no-update"** in the category

■ **MP Tool**	■ **Controller ISP**
☐ **Yield Issue**	■ **Yield Issue**
☐ **Flash Issue**	☐ **Flash Issue**
☐ TLC Flash	☐ TLC Flash
☐ Samsung Flash	☐ Samsung Flash
☐ Toshiba/Sandisk Flash	☐ Toshiba/Sandisk Flash
☐ Intel/Micron Flash	☐ Intel/Micron Flash
☐ Hynix Flash	☐ Hynix Flash
☐ Others	☐ Others
■ 3D NAND Flash	■ 3D NAND Flash
☐ Samsung Flash	☐ Samsung Flash
☐ Toshiba/Sandisk Flash	☐ Toshiba/Sandisk Flash
■ Intel/Micron Flash	■ Intel/Micron Flash
☐ Hynix Flash	☐ Hynix Flash
☐ Others	☐ Others
☐ **MP Tool Bug Fix**	☐ **ISP Bug Fix**
☐ **MP Tool New Function**	☐ **Feature Enhance**
☐ **Feature Enhance**	

ISP Revision History

Package	ISP version	MP Tool Version	RDT version	Note
Q1124A	Q1115A0	Q1121A	Q1116A0	ISP 1 First formal release to support Intel/Micron B17.

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date" .

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.